



22. Sector – Cortanovci (km 1,241.6 – 1,235.0)



22. Cortanovci – Existing situation




22. Cortanovci – Existing situation





Navigation problems:

- Upstream: narrow fairway in the bend due to point bar
- Downstream: unstable river bed




22. Cortanovci – option 1: Sills





22. Cortanovci – option 2: Dredging

- Km 1239.4-1240.4 : 68,901 m³



22. Cortanovci – option 4: dredging+sills



22. Cortanovci – options 1, 2 and 4

- Navigation:
 - increased flow in the fairway channel;
 - additional dredging is required.
- Environment:
 - Upstream small part of point bar is eroded;
 - Preserved river dynamics in the sector.
- Cost:
 - Upstream: sills are about 50-100 m wide and 3 m high;
 - Downstream: sills are 70 m and 150 m wide and 2 m high
- Optimization of:
 - Sill crest level;
 - Exact location of structures.

22. Cortanovci - MCA

Options	Effectiveness	Environment	Cost
Option 1 – sills	Limited	Limited	Limited
Option 2 – dredging	Low	Limited	Limited
Option 4 – dredging + two sills	Limited/low	Limited	Limited/low